From: Philip Turner To: Michele Burgess

Gary Moore; Nancy Jones; Janine Dinan; Gilberto Irizarry; Jon Rauscher; Alethea Tsui-Bowen

Subject: Re: Fw: Question Date: 10/24/2012 01:22 PM

The interest here is not for screening levels, but for actual clean-up values.

## Michele Burgess---10/24/2012 12:50:06 PM---Hi Gary, The Regional Screening. Levels Table for Chemical Contaminants at Superfund sites (RSLs) are

From: Michele Burgess/DC/USEPA/US

To: Gary Moore/R6/USEPA/US@EPA
Cc: Nancy Jones/DC/USEPA/US@EPA, Janine Dinan/DC/USEPA/US@EPA, Gilberto Irizarry/DC/USEPA/US@EPA, Philip Turner/R6/USEPA/US@EPA, Jon Rauscher/R6/USEPA/US@EPA, Alethea Tsui-Bowen/R6/USEPA/US@EPA

Date: 10/24/2012 12:50 PM Subject: Re: Fw: Question

#### Hi Gary,

The Regional Screening Levels Table for Chemical Contaminants at Superfund sites (RSLs) are used to screen chemicals in for remedial sites. The target risk levels are set at 10-6 for carcinogens and HQ=1 for noncarcinogens.

The Removal program in OEM have set them at 10-4 and 3, respectively for removal actions.

As you may know, Region 6 is one of the originators of this Table. http://www.epa.gov/region6/6pd/rcra\_c/pd-n/screen.htm

> I have entered the screening levels from the Region 6 RSL Table. We have two values, residential and industrial scenarios. The first value would be residential and the second is industrial.

Arsenic 0.39 mg/kg, 1.6 mg/kg Lead 400 mg/kg, 800 mg/kg Benzo(a)Anthracene 0.15 mg/kg, 2.1 mg/kg Benzo(a)Pyrene 0.015 mg/kg,0.21mg/kg 2-Methylnapthalene 230 mg/kg,2200 mg/kg

Napthalene 3.6 mg/kg, 18 mg/kg

[attachment "Copy of master\_sl\_table\_run\_MAY2012.xls" deleted by Philip Turner/R6/USEPA/US]

I have also cc'd your regional risk assessors, in case you need to reach out to them for your site.

Take care. Michele F. Burgess, Ph.D. Office of Superfund Remediation, & Technology Innovation Assessment & Remediation Division Science Policy Branch Work: 703-603-9003

# ▼ Nancy Jones---10/24/2012 01:24:46 PM---see below - can you help? -----Forwarded by Nancy Jones/DC/USEPA/US on 10/24/2012 01:24 PM -----

From: Nancy Jones/DC/USEPA/US
To: Michele Burgess/DC/USEPA/US@EPA

Date: 10/24/2012 01:24 PM Subject: Fw: Question

### see below - can you help?

---- Forwarded by Nancy Jones/DC/USEPA/US on 10/24/2012 01:24 PM -----

From: Gary Moore/R6/USEPA/US To: jones.nancy@epa.gov Date: 10/24/2012 01:22 PM

Subject: Question

### Nancy:

I am working on this industrial site. I am trying to find out Remedial Cleanup levels of recent sites for Soil contamination.

The Contaminants are:

Arsenic Lead Benzo(a)Anthracene Benzo(a)Pyrene 2-Methylnapthalene Napthalene

Gary Moore Federal On-Scene Coordinator EPA Region 6

Cell: 214-789-1627 Work: 214-665-6609

email: moore.gary@epa.gov